

#### 4 Individual axis switch-off for external axes (continued)




Fig. 14 Outputs




Fig. 15 Inputs

## 4 Individual axis switch-off for external axes (continued)




Fig. 16 Cross connections